

1/2

## SilverTape AM9611 COATING 66 Product Information 01.2015

## SilverTape AM9611

The AM9611 allows a very good adhesion on a wide variety of automotive applications and especially on LSE substrates (ceramic / silicones). Other features are: very good shear strength, good inner strength, very good long term stability and very good adaptability to the bonding surfaces. Because of the viscoelastic properties, tensions in the adhesive seam are perfectly removed and allow a very durable bonding.

Red PE liner			Thickness:		1,1 mm (0.047 inch) ±10%
Coating 66			Core:		Conformable acrylic
Selfstick			Adhesive:		Acrylic coating 66
Coating 66			Density:		600kg/m <sup>3</sup> (37lb/ft <sup>3</sup> )
Coating of			Color:		Black
			Liner:		Red PE liner or white paper liner
			Solvent Resistance:		Excellent
			UV Resistance:		Excellent
			Temperature Resistance:		
				Minimum	-40°C (-40°F)
				Short term	120°C (248°F)
				Long term	90°C (194°F)

90° Peel Adhesion	N/10mm (Ib/in)	46 (26)		ASTM D3330
Dynamic Shear Strength	kPa (Ib/in²)	710 (103)		ASTM D-1002
Normal Tensile	kPa (Ib/in²)	650 (94)		ASTM D-897
Static Shear Strength	Grams Weight that ½ square inch will hold for 10,000 minutes (7 days)	22°C (72°F) 66°C (150°F) 93°C (200°F) 121°C (250°F) 177°C (350°F)	1000 500 500 250	ASTM 3654

Suitable for:

- various medium and low surface energy plastics, silicones, teflon, powder coatings, clearcoats, ceramic car paints\* Available sizes:

- jumbo: 900mm x 330 meters (core 3")
- log: 900mm x 33/66 meters (core 3")
- slit roll: 4 250mm x 33/66 meters (core 3")
- spool roll: 5 25mm x max 900 meters (core 6")



2/2

**SilverTape AM9611** COATING 66 Product Information 01.2015

Application Guidelines	Every good bond starts with proper surface preparation. This preparation consists of several steps, such as cleaning, abrading, applying pressure, the use of a primer and the right working environment. It is important to ensure your work area to be lean and free from dust and contaminants. A minimum temperature of 15 °Celsius is required.				
Cleaning	To clean your light and medium contaminated substrates, AFTC offers the AFTC SilverClean or an isopropanol/alcohol solution (IPA) is acceptable. When cleaning your substrate, a tear free, light colored paper towel is required. Wipe the substrate in one direction using the one cloth method (one cloth with cleaner) or a two cloth method (one cloth with cleaner and one dry cloth to follow) is acceptable if you are short on time. Repeat these steps until your cloth is clean and free of any contaminants. For heavily contaminated substrates, use a cleaning agent such as MEK, Heptan or Acetone. These cleaning agents may leave a residue. which would have to be removed using the IPA cleaner.				
Abrasion	When bonding to raw aluminum, abrading of the surface is a must. The oils used in the waltzing of the aluminum are pressed into the pores of the material. To remove these oils, that will influence the bond, we recommend using the AFTC SilverPads. These abrasive pads ensure the proper level of abrasion without damaging your substrates. Besides raw aluminum, abrading is a method utilized to help improve your bond. After the abrasion process is completed, remove any residue using an IPA cleaner following the methods mentioned above.				
Primer	The use of a primer is recommended when bonding tosome low surface energy substrates. Examples include, different types of polymers,powder coated metals, or porous materials such as wood, cork, stone or concrete. Primersare also used to help speed up your production process. The AFTC SilverTape line can take up to 72 hours to reach its end-strength. The use of a primer ensures the end-strength will be achieved within 20 minutes. AFTC offers two primers; the primer 33 and the primer 101. Determining which one of these primers is suitable for your application ultimately depends on the substrates and environmental influences. Your AFTC technical support will gladly advise you which primer to use.				
Pressure	AFTC SilverTapes are pressure sensitive adhesives. Therefore, a minimum amount of pressure is required on the bond line to ensure the maximum adhesion to your substrates. This pressure should be applied in a rolling fashion. A hand roller or mechanical presserare the preferred methods. The pressure on the bond line must be a minimum of at least 10N/cm <sup>2</sup> .				
Storage & Shelf life	Please make sure that the tape is stored in its original packaging, in a dry place and at a preferable temperature between 4 °C and 38 °Celsius. When the tape is stored under the proper conditions, the tape has a shelf life of 18 months.				
*Important Information	All technical data in this product data sheet are based on AFTC's experience and external testing institutes. These values are representative of the overall performance. These data sheets are NOT to be used for specification purposes or for your own specific application. It is your responsibility to test whether the tape is suitable for your application or project. AFTC will NOT be held liable for any information provided on this data sheet. You must follow the rules and regulations that are applicable in the state, county or country where the AFTC product(s) are being used. If you have any questions regarding the use of the AFTC SilverTape acrylic foam tapes, please contact our technical sales team. For questions on the standard warranty, please review our standard delivery terms and conditions. For all otherwarranties, please review all documents that should have been agreed to in writing prior to the sale between AFTC and the customer. SilverTape <sup>®</sup> is a brand name of AFTC.				